



PS500


Quick Operation Guide



Switch On



Switch Off



OFF 3





OFF 2

OFF 1

Backlight On

Max

Min



Reset

Confidence Signal

Every 15s



Manual Datalog




Pump




Alarm Indicators





Gas Alarm Acknowledge





Self Test




Flow Fault



Zero Fault



Calibration Overdue



Battery Life



Charging

